

The New Piper Aircraft Inc.

PA-31-300/310/325 NAVAJO
PA-31-350 CHIEFTAIN
PA-31-350 T1020

Publication Number	Subject	Issue Date	Revision
VSP 1	Avco Lycoming Service Bulletin No. 385C	03/08/76	
VSP 3	AVCO Lycoming Service Bulletin No. 406	02/25/77	
VSP 7	Goodyear Aerospace Service Bulletin No. FT-77-1 Rev. B	10/10/77	
VSP 8	Scott Aviation October 1977 Letter: Scott Aviation	12/27/77	
VSP 23	Avco Lycoming Service Bulletin No. 450	09/25/80	
VSP 24	Parker Hannifin Corporation Product Reference Memo (PRM) Nos. 13 and 14	10/22/80	
VSP 29	Avco Lycoming Service Bulletin No. 452	02/27/81	
VSP 30	Bendix Service Bulletins 599A, 609A, 610, 613, 614	05/20/81	
VSP 31	Bendix Service Bulletin No. 618	08/07/81	
VSP 33	Bendix Service Bulletins 611, 616, 617, 619	12/18/81	
VSP 35	Global Navigation Service Bulletin No. 21	04/21/82	
VSP 36	Avco Lycoming Engine Oil Level Gauge Gasket Replacement	06/14/82	
VSP 37	Bendix Service Bulletins 615, 620, 621	07/07/82	
VSP 57	Airborne Service Letter No. 29	01/10/86	
VSP 61	AVCO Lycoming Service Bulletin No. 469	03/28/86	
VSP 65	McCreary Tire & Rubber Company Memo to: McCreary Distributors	07/10/86	
VSP 69	Bendix Service Bulletin No. 629	09/12/86	
VSP 71	Narco Avionics Service Bulletin No. ELT-14	12/16/86	
VSP 75	Avco Lycoming Service Letter No. L218 and Service Instruction No. 1059C, No. 1110C and No. 1257E	08/14/87	
VSP 80	AVCO Lycoming Service Letter No. L213A and Service Instructions No. L1059C	09/23/87	
VSP 81	Bendix/King Installation Bulletins No. 250 and No. 260	09/28/87	
VSP 99	Aeroquip Service Bulletin 001R1	10/19/89	
VSP 105	Lycoming Service Instruction No. 1447A	03/25/91	
VSP 109	DUKES INC. Mandatory Service Bulletin No. 0005	04/14/95	
VSP 118	Textron Lycoming Service Instruction No. 1267C	04/19/99	
VSP 119	Textron Lycoming Service Bulletin No. 480C	04/19/99	
VSP 144	Lycoming Service Bulletin No. 552	08/16/02	
VSP 148	Lycoming Service Bulletin No. 554 and Lycoming Service Bulletin No. 554 Supplement No. 1	10/03/02	
SA 31-1	Nayak Fuel Vent System Modification	06/15/82	

The New Piper Aircraft Inc.

**PA-31-300/310/325 NAVAJO
PA-31-350 CHIEFTAIN
PA-31-350 T1020**

Publication Number	Subject	Issue Date	Revision
SA 31-32	Installation of Aft Facing Seat Limitation Placard	06/06/85	